

Overview of UTAX products that are not affected by the security vulnerabilities.

[JVN#46345126 || CVE-2022-41798 || CVE-2022-41807 || CVE-2022-41830]

(Status: 15.11.2022)

UTAX-Model
UTAX 355ci
UTAX 3555i
UTAX 4555i
UTAX 5555i
UTAX 2506ci
UTAX 3206ci
UTAX 4006ci
UTAX 5006ci
UTAX 6006ci
UTAX 2507ci
UTAX 3207ci
UTAX 4007ci
UTAX 5007ci
UTAX 6007ci
UTAX 4056i
UTAX 5056i
UTAX 6056i
UTAX 5057i
UTAX 6057i
UTAX P-6040DN
UTAX 2508ci
UTAX 3508ci
UTAX 4008ci
UTAX 5008ci
UTAX 6008ci
UTAX 7008ci
UTAX 5058i
UTAX 6058i
UTAX 7058i
UTAX 2550ci
UTAX 2500ci
UTAX P-3521MFP
UTAX P-3527wMFP
UTAX P-4020MFP
UTAX P-4025wMFP
UTAX P-4026iwMFP
UTAX P-3522DW
UTAX P-4020DN
UTAX P-4020DW
UTAX P-C3060MFP
UTAX P-C3065MFP
UTAX P-C3560iMFP

IF IT WORX, IT'S



UTAX P-C3565iMFP
UTAX 356ci
UTAX 357ci
UTAX P-C3062iMFP
UTAX P-C3066iMFP
UTAX P-C3562iMFP
UTAX P-C3566iMFP
UTAX P-C3062DN
UTAX P-C3562DN
UTAX P-C4072DN
UTAX P-C3061DN
UTAX P-C3560DN
UTAX P-C4070DN
UTAX 6505ci
UTAX 7505ci
UTAX 7006ci
UTAX 8006ci
UTAX 7307ci
UTAX 8307ci
UTAX 300ci
UTAX 350ci
UTAX 400ci
UTAX 301ci
UTAX 302ci
UTAX 352ci
UTAX 402ci
UTAX 502ci
UTAX P-4531MFP
P-4531iMFP
P-4536MFP
P-4536iMFP
P-5536iMFP
P-6038iMFP
P-4030iMFP
UTAX P-4035iMFP
UTAX P-4030MFP
UTAX P-4035MFP
UTAX CLP 3550
UTAX P-C2655wMFP
UTAX P-C2650DW
UTAX CD 1430
UTAX 3060i
UTAX 3560i
UTAX 3061i
UTAX 3561i
UTAX 3262i
UTAX 4062i
UTAX 3263i
UTAX 4063i
UTAX 3005ci

IF IT WORX, IT'S



UTAX 3505ci
UTAX 4505ci
UTAX 5505ci
UTAX 6555i
UTAX 8055i
UTAX 7056i
UTAX 8056i
UTAX 7057i
UTAX 8057i