

Overview of TA Triumph-Adler products that are not affected by the security vulnerabilities.  
 [JVN#46345126 || CVE-2022-41798 || CVE-2022-41807 || CVE-2022-41830]

(Status: 15.11.2022)

TA-Model
TA 355ci
TA 355i
TA 455i
TA 555i
TA 2506ci
TA 3206ci
TA 4006ci
TA 5006ci
TA 6006ci
TA 2507ci
TA 3207ci
TA 4007ci
TA 5007ci
TA 6007ci
TA 4056i
TA 5056i
TA 6056i
TA 5057i
TA 6057i
TA P-6040DN
TA 2508ci
TA 3508ci
TA 4008ci
TA 5008ci
TA 6008ci
TA 7008ci
TA 5058i
TA 6058i
TA 7058i
TA 2550ci
TA 2500ci
TA P-3521MFP
TA P-3527wMFP
TA P-4020MFP
TA P-4025wMFP
TA P-4026iwMFP
TA P-3522DW
TA P-4020DN
TA P-4020DW
TA P-C3060MFP
TA P-C3065MFP

TA P-C3560iMFP
TA P-C3565iMFP
TA 356ci
TA 357ci
TA P-C3062iMFP
TA P-C3066iMFP
TA P-C3562iMFP
TA P-C3566iMFP
TA P-C3062DN
TA P-C3562DN
TA P-C4072DN
TA P-C3061DN
TA P-C3560DN
TA P-C4070DN
TA 6505ci
TA 7505ci
TA 7006ci
TA 8006ci
TA 7307ci
TA 8307ci
TA 300ci
TA 350ci
TA 400ci
TA 301ci
TA 302ci
TA 352ci
TA 402ci
TA 502ci
P-4531MFP
P-4531iMFP
P-4536MFP
P-4536iMFP
P-5536iMFP
P-6038iMFP
TA P-4030iMFP
TA P-4035iMFP
TA P-4030MFP
TA P-4035MFP
TA CLP 4550
TA P-C2655wMFP
TA P-C2650DW
TA DC 2430
TA 3060i
TA 3560i
TA 3061i
TA 3561i
TA 3262i
TA 4062i
TA 3263i
TA 4063i

TA 3005ci
TA 3505ci
TA 4505ci
TA 5505ci
Pro 15050c
TA 6555i
TA 8055i
TA 7056i
TA 8056i
TA 7057i
TA 8057i